

FIG.1



Tadashi HIBINO, et al.
STEERING LOCKING DEVICE
October 24, 2005
Darryl Mexic 202-293-7060
Q91007
I of 17



Tadashi HIBINO, et al.
STEERING LOCKING DEVICE
October 24, 2005
Darryl Mexic 202-293-7060
Q91007
2 of 17

FIG.3





FIG.4



Tadashi HIBINO, et al.
STEERING LOCKING DEVICE
October 24, 2005
Darryl Mexic 202-293-7060
Q91007
4 of 17

FIG.5






FIG.6




Tadashi HIBINO, et al.
STEERING LOCKING DEVICE
October 24, 2005
Darryl Mexic 202-293-7060
Q91007
6 of 17

FIG.7




Tadashi HIBINO, et al.
STEERING LOCKING DEVICE
October 24, 2005
Darryl Mexic 202-293-7060
Q91007
7 of 17

FIG.8



Tadashi HIBINO, et al.
STEERING LOCKING DEVICE
October 24, 2005
Darryl Mexic 202-293-7060
Q91007
8 of 17

FIG.9



Tadashi HIBINO, et al.
STEERING LOCKING DEVICE
October 24, 2005
Darryl Mexic 202-293-7060
Q91007
9 of 17

**FIG.10** 






FIG.11




Tadashi HIBINO, et al.
STEERING LOCKING DEVICE
October 24, 2005
Darryl Mexic 202-293-7060
Q91007
11 of 17

FIG.12




Tadashi HIBINO, et al.
STEERING LOCKING DEVICE
October 24, 2005
Darryl Mexic 202-293-7060
Q91007
12 of 17

FIG.13




Tadashi HIBINO, et al.
STEERING LOCKING DEVICE
October 24, 2005
Darryl Mexic 202-293-7060
Q91007
13 of 17

FIG.14




Tadashi HIBINO, et al.
STEERING LOCKING DEVICE
October 24, 2005
Darryl Mexic 202-293-7060
Q91007
14 of 17

**FIG.15** 




Tadashi HIBINO, et al.
STEERING LOCKING DEVICE
October 24, 2005
Darryl Mexic 202-293-7060
Q91007
15 of 17

FIG.16



Tadashi HIBINO, et al.
STEERING LOCKING DEVICE
October 24, 2005
Darryl Mexic 202-293-7060
Q91007
16 of 17

FIG.17



Tadashi HIBINO, et al.
STEERING LOCKING DEVICE
October 24, 2005
Darryl Mexic 202-293-7060
Q91007
17 of 17